EXHIBIT A



Preliminary Information

PIC6244B Diagnostic Aid For Vehicles With Shift To Park Message And All DTCs P1AEE P1AEF P1AF0 P1AF2 P1E22

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Transmissions.
Chevrolet	Volt	2016 - 2019	All	All	All	5ET50 (MKV)
Chevrolet	Malibu	2016 - 2019	All	All	All	5ET50 (MKE)
Buick	LaCrosse	2016 - 2019	All	All	All	5ET50 (MKV)

Involved Region or Country	North America, Korea, China
Condition	Some customers may experience a Shift to Park message with DTCs P1AEE, P1AEF, P1AF0, P1AF2, P1E22.
Cause	If all five DTCs are present, then there is an internal concern with the drive unit (transmission). Important: If only two or three of these DTCs are present, then proceed with normal SI diagnostics as the concern may not be internal to the drive unit.

Correction:

The drive unit (transmission) will need to be replaced. Do not attempt any internal at this time as the drive unit is on exchange.

Please refer to the last version of PIP5321 for the Volt Transmission Exchange.

Please refer to the lasted version of PIP5390 for the Malibu Transmission Exchange.

Version History

Version	3
	01/09/2017 - Created
Modified	10/17/2017 - Updated to add 2018 model Year
	9/17/2018 - Updated to add 2019 model year.















